GL: Emergency Relief – SHOPP Emergency Response Program (TIP ID – VAR170008)

Last updated with TIP Revision 2021-02

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
	MRN			Near Sausalito, at 0.1 mile south of Alexander Avenue.	1492J		201.131	19/20	\$3,559	\$0	\$0	\$0	\$0	\$837	\$850	\$100	\$850	\$13	\$909	\$3,559
				Restore damaged drainage systems.					, -,	, -	• -	, -	, -	,	,	,	,	, -	,	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
04	SM	280	20.3/20.6		1499H	4J080	201.131	19/20	\$2,769	\$0	\$0	\$0	\$0	\$390	\$650	\$78	\$390	\$168	\$1,093	\$2,769
•					•	٦	ime Extensi	on Total	\$6,328	\$0	\$0	\$0	\$0	\$1,227	\$1,500	\$178	\$1,240	\$181	\$2,002	\$6,328
	ALA			In Hayward, at Industrial Parkwal Overcrossing No.33-0398. Repair bridge by replacing exterior girder, adjoining deck, and barrier rail, and install advanced warning signs.		1W210		20/21	\$0	\$2,800	\$0	\$0	\$0	\$0	\$0	\$0	\$800	\$0	\$2,000	\$2,800
04	ALA	580		In Oakland, at Harrison Street Undercrossing No. 33- 0289S. Construct wrought iron fencing with secured access gates.		1W540	201.130	20/21	\$ 0	\$1,190	\$0	\$0	\$0	\$0	\$0	\$0	\$270	\$20	\$900	\$1,190
04	ALA	880		In Oakland, at 16th Avenue Overcrossing No. 33- 0137. Repair spalled surfaces on the soffit, secure soffit access, and clear out the burned material.	2907F	1W420	201.130	20/21	\$0	\$565	\$0	\$0	\$0	\$0	\$0	\$0	\$155	\$0	\$410	\$565
04	CC	24	6.6/7.4	In Lafayette, on westbound Route 24, from 1.1 miles west to 0.3 mile west of Pleasant Hill Road Undercrossing. Repair settlement by injecting polyurthane and grout in voids, replace culverts, and repair pavement.	2907H	0W610	201.130	20/21	\$0	\$1,260	\$0	\$0	\$0	\$0	\$0	\$20	\$280	\$20	\$940	\$1,260
04	MRN	1	10.7/11.0		2032Q	0AA48	201.131	20/21	\$311	\$1,499	\$0	\$0	\$0	\$0	\$227	\$84	\$336	\$31	\$1,132	\$1,810
04	MRN	101	3.5/4.8	Near Mill Valley, on northbound Route 101 at Richardson Bay Bridge and Separation No. 27-0010. Repair expansion joints.	2907J	1W580	201.130	20/21	\$0	\$1,040	\$0	\$0	\$0	\$0	\$0	\$0	\$260	\$0	\$780	\$1,040
04	MRN	1		Near Five Brooks, at Giacomini Creek Bridge No. 27-0122. Four-year mitigation plant establishment for emergency project EA 4K850.	2032E	0AA44	201.131	20/21	\$453	\$1,513	\$0	\$0	\$0	\$0	\$400	\$53	\$650	\$15	\$848	\$1,966
04	NAP	29	33.5/48.6	In and near Calistoga, from Lakemead Lane to Lake County line; also in and near Santa Rosa in Sonoma County on Route 12, from 0.1 mile east of Acacia Lane to Hoff Road (PM 19.3/25.8). Repair or replace guardrails, ditches, signs, fencing, drainage and electrical facilities, remove debris and hazardous trees, repair pavement, and install erosion control in fire damaged areas.		1W630	201.130	20/21	\$0	\$5,320	\$0	\$0	\$0	\$0	\$0	\$20	\$1,200	\$100	\$4,000	\$5,320
04	NAP	121		In Napa and Solano Counties on Routes 121 and 128 at various locations. Repair culverts, retaining walls, and pavement, remove hazardous trees, replace guardrails, and install erosion control in fire damaged areas.		1W480	201.130	20/21	\$0	\$10,420	\$0	\$0	\$0	\$0	\$0	\$0	\$2,400	\$20	\$8,000	\$10,420
04	SCL	35		Near Los Gatos, at 1.8 miles north of Black Road. Stabilize slope and improve drainage systems.	2035F	0W170	201.130	20/21	\$0	\$1,700	\$0	\$0	\$0	\$0	\$0	\$0	\$400	\$0	\$1,300	\$1,700
04	SCL	130	11.2/22.5	Near San Jose, from Quimby Road to Observatory Peak Road. Repair damaged culverts and pavement, replace signs and delineators, and install erosion control in fire damaged areas.		1W620	201.130	20/21	\$0	\$6,010	\$0	\$0	\$0	\$0	\$0	\$60	\$1,350	\$100	\$4,500	\$6,010

April 28, 2021 1 of 4

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
				Near San Jose, from 0.8 mile west of Smith Creek		1W510		20/21	\$0	\$2,720	\$0	\$0	\$0	\$0	\$0	\$20	\$600	\$100	\$2,000	\$2,720
				Bridge to 1.0 mile west of Observatory Peak Road.					, .	, ,	, -	• -	, -	, .	• •		,	,	, ,	, ,
				Repair or replace guardrails, signs, ditches,																
				drainage and electrical facilities, remove debris and																
				hazardous trees, and install erosion control in fire																
				damaged areas.																
04	SCL	101		In Mountain View, at North Shoreline Boulevard	2804C	0W680	201.130	20/21	\$0	\$770	\$0	\$0	\$0	\$0	\$0	\$0	\$200	\$0	\$570	\$770
				onramp to southbound Route 101. Replace culverts,																
				inject polyurethane foam, and reconstruct																
04	SCL	101		Near Gilroy, at Sargent Bridge and Overhead No. 39-	1452D	4J030	201.131	20/21	\$1,482	\$3,090	\$0	\$0	\$0	\$650	\$780	\$52	\$900	\$87	\$2,103	\$4,572
04	SCL	101		0006L. Permanent restoration of roadway settlement	14336	43030	201.131	20/21	φ1,40Z	\$3,090	φυ	φυ	φυ	\$000	φ/ου	φ52	φ900	φοι	φ <u>2,103</u>	Φ4,37 Z
				and southern abutment wingwall movement.																
04	SF	101		In the City and County of San Francisco, at Central	2907M	1W980	201.130	20/21	\$0	\$1,090	\$0	\$0	\$0	\$0	\$0	\$10	\$270	\$0	\$810	\$1,090
	٥.			Viaduct No. 34-0077. Replace the damaged concrete			2011100	20,21	••	ψ 1,000		••	**	**	••	•.•	42.0	**	ΨΟΙΟ	Ψ1,000
				barrier and guardrail.																
04	SM	1	0.0/13.5	•	2906E	1W520	201.130	20/21	\$0	\$1,080	\$0	\$0	\$0	\$0	\$0	\$20	\$260	\$50	\$750	\$1,080
				Pescadero Creek Road. Repair or replace																
				guardrails, signs, ditches, drainage and electrical																
				facilities, remove debris and hazardous trees, and																
				install erosion control in fire damaged areas.																
0.4	011				4.450.1	014070	224 424	00/04	* 4 0 7 0	40.000	**	**	**	# =00	A =10	400	***	407	40.070	A= 0=0
04	SM	82		In South San Francisco, at 0.1 mile north of Francisco	1450J	0K670	201.131	20/21	\$1,270	\$3,806	\$0	\$0	\$0	\$500	\$710	\$60	\$800	\$27	\$2,979	\$5,076
				Drive. Permanent embankment restoration by installing																
				retaining wall and drainage improvements.																
04	SOL	37		Near Vallejo, at the Route 37/29 Separation No. 23-	2904 1	0W580	201.130	20/21	\$0	\$582	\$0	\$0	\$0	\$0	\$0	\$0	\$152	\$0	\$430	\$582
04	OOL	0,		0218. Replace expansion joint system.	23040	011300	201.100	20/21	ΨΟ	Ψ302	Ψ	Ψ0	Ψ	Ψ σ	Ψ0	**	Ψ102	Ψ	Ψ-00	ΨOOZ
04	SOL	80	20.9/25.3		2905E	1W490	201.130	20/21	\$0	\$3,290	\$0	\$0	\$0	\$0	\$0	\$0	\$750	\$40	\$2,500	\$3,290
				Texas Street to Alamo Drive. Repair or replace					•	, , , , ,	, -	• •	, -	, .	* -	, ,	,	, -	, ,	, , , , ,
				guardrails, ditches, drainage and electrical facilities,																
				signs and fencing, replace oleanders in the median,																
				remove debris and hazardous trees, and install																
				erosion control in fire damaged areas.																
2.1					222216	4344	224 422	20101	•	****	**	•	40	40	•		4454	•	A 4 = 0	****
04	SON	1		Near Jenner, at 0.3 mile north of Pacific View Drive.	2906K	1W550	201.130	20/21	\$0	\$600	\$0	\$0	\$0	\$0	\$0	\$0	\$150	\$0	\$450	\$600
				Construct sheet pile retaining wall, stabilize slope																
				with Rock Slope Protection (RSP), replace culvert,																
04	SON.	1	27 3/31 5	and reconstruct roadway. Near Jenner, from 0.9 mile north of Meyers Grade	2906B	1W500	201.130	20/21	\$0	\$20,890	\$0	\$0	\$0	\$0	\$0	\$60	\$4,750	\$80	\$16,000	\$20,890
04	3011	•	27.3/31.3	Road to 1.5 miles south of Fort Ross Road. Repair	29000	144300	201.130	20/21	φυ	φ20,090	φυ	φυ	Ψυ	Ψυ	φυ	\$60	φ4,7 30	φου	φ10,000	φ 2 0,090
				or replace guardrails, drainage systems, electrical																
				facilities, signs and fencing, repair damaged																
				retaining walls, remove debris and hazardous trees,																
				and install erosion control in fire damaged areas.																
04	SON	1	15.1/15.7	Near Carmet, from 0.1 mile to 0.7 mile north of Calle	0748E	0A020	201.131	20/21	\$17,698	\$40,824	\$0	\$0	\$0	\$0	\$1,800	\$500	\$5,000	\$15,398	\$35,824	\$58,522
				Del Sol. Realign roadway near Gleason Beach.																
04	SON	1	26.7/27.0	Near Jenner, from 0.3 to 0.4 mile north of Myers Grade	0482T	0J300	201.131	20/21	\$4,810	\$26,082	\$0	\$0	\$0	\$2,106	\$2,496	\$208	\$3,600	\$243	\$22,239	\$30,892
				Road. Permanent restoration of roadway slipouts.																
0.4	001	101		Near Database worth of Donney David Continuous (1)	04040	0.14.04	204 424	20/04	ФО.	0440	C O	# 0	60	00	# 0	C O	#440	# 0	фО.	¢4.40
04	SON	101		Near Petaluma, north of Pepper Road. Environmental	0481G	UJ101	201.131	20/21	\$0	\$140	\$0	\$0	\$0	\$0	\$0	\$0	\$140	\$0	\$0	\$140
04	ΔΙΛ	580		mitigation for project EA 0J100.	1/610	0P120	201 121	21/22	\$752	0.2	\$5.400	¢Ω	0.2	\$750	\$040	\$60	\$1.201	\$50	\$3.140	\$6,152
04		500		·	14010	01-120	201.131	21/22	ψ132	φυ	ψ5,400	φυ	φυ	φ132	φυ4υ	φυυ	ψ1,201	φου	ψ3, 140	ψ0,132
				· ·																
				measures.																
04	ALA	580		Near Livermore, at 0.3 mile west of Stonecut Underpass (PM R4.3L). Restore eroded embankment slope in the eastbound direction and install erosion control	1461D	0P120	201.131	21/22	\$752	\$0	\$5,400	\$0	\$0	\$752	\$949	\$60	\$1,201	\$50	\$3,140	\$6,1

April 28, 2021 2 of 4

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
				In Fremont, at the northbound offramp to Mission		0Q680		21/22	\$750	\$945	\$3,946	\$0	\$0	\$750	\$885	\$60	\$1,033	\$5	\$2,908	\$5,641
-				Boulevard. Stabilize storm damaged embankment.		,			,	, -	, , , ,	, -	, -	,	,	,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, -	, , ,	¥ = , =
04	ALA	92		In Hayward, at the westbound connector from	2028K	0Q450	201.131	21/22	\$285	\$363	\$862	\$0	\$0	\$285	\$347	\$16	\$191	\$10	\$661	\$1,510
				northbound Route 880. Restore eroded embankment						·		·			·	·	·	·	·	. ,
				and extend existing concrete barrier.																
04	MRN	1		Near Stinson Beach, at 0.7 mile south of Panoramic	2034J	0W130	201.131	21/22	\$0	\$479	\$1,845	\$0	\$0	\$0	\$454	\$25	\$500	\$31	\$1,314	\$2,324
-				Highway. Implement permit requirements including					•	,	, , , -	, -	, -	•	, -	, -	•	, -	, ,-	, ,-
				plant establishment, noxious weed control, seed																
				collection and propagation, and biological																
				monitoring for emergency project EA 0P130.																
				3 3 3 3 3 4 3																
04	NAP	29	11.6/13	.0 In Napa, from First Street to 0.1 mile south of Redwood	2022G	0Q820	201.131	21/22	\$1,437	\$0	\$16,619	\$0	\$0	\$1,437	\$1,792	\$152	\$1,228	\$44	\$13,403	\$18,056
				Road/Trancas Street. Repair culvert.					,	·				. ,	,		,		,	
04	NAP	12	2.1/2.6	·	2021F	0Q690	201.131	21/22	\$308	\$470	\$1,779	\$0	\$0	\$308	\$320	\$150	\$400	\$134	\$1,245	\$2,557
				the Solano County line. Repair storm damaged slopes						·	,		·			·	·	·	. ,	. ,
				at two locations with Rock Slope Protection (RSP) and																
				restore ditches.																
04	SCL	9		In Saratoga, north of Pierce Road (PM 5.97). Install	1464D	2K280	201.131	21/22	\$484	\$0	\$1,589	\$0	\$0	\$130	\$318	\$36	\$315	\$10	\$1,264	\$2,073
_				Rock Slope Protection (RSP) and replace culvert.					,	* -	, ,	, -	, -	,	,	,	•	, -	, , -	, ,
04	SM	1		Near Half Moon Bay, at 1.1 miles north of Santa Cruz	1450H	0K570	201.131	21/22	\$770	\$0	\$1,492	\$0	\$0	\$300	\$400	\$70	\$500	\$2	\$990	\$2,262
_				County line. Repair slope washout by constructing a						* -	, ,	, ,	, .	,		, -	,	,	, , , , ,	, , -
				soldier pile wall and upgrading the drainage system.																
04	SM	84		Near La Honda, at 1.2 miles north of Madera Lane	1455B	2K610	201.131	21/22	\$936	\$400	\$1,292	\$0	\$0	\$936	\$390	\$10	\$250	\$147	\$895	\$2,628
-				(north). Repair slope washout and place Rock Slope					,	,	, ,	, ,	, .	,	,	, -	, , ,	,	, , , , ,	, ,
				Protection (RSP) on existing embankment to prevent																
				further erosion.																
04	SON	101		Near Cloverdale, at 0.4 mile south of the Mendocino	1462P	2K350	201.131	21/22	\$840	\$541	\$3,304	\$0	\$0	\$840	\$413	\$128	\$459	\$225	\$2,620	\$4,685
	_			County line. Restore slope, rebuild damaged gutter and					,		, , , , ,	, ,	, .	,	•	,	, , ,		, , , , ,	, ,
				install erosion control measures.																
04	CC	680	19.2/19		2028N	0Q780	201.131	22/23	\$608	\$0	\$818	\$2,950	\$0	\$608	\$752	\$66	\$807	\$24	\$2,119	\$4,376
				Undercrossing No. 28-0178 and Concord Avenue						·		. ,	·			·	·	·	. ,	. ,
				Undercrossing No. 28-0190. Stabilize storm damaged																
				abutment slopes by paving with concrete.																
04	NAP	121	16.0/16	.1 Near Napa, at Wooden Valley Road. Repair	2022F	0Q810	201.131	22/23	\$0	\$902	\$1,460	\$2,060	\$0	\$902	\$1,287	\$173	\$661	\$86	\$1,313	\$4,422
				pavement, replace drainage systems, and upgrade								. ,			, ,	·	·		. ,	. ,
				guardrail.																
04	SM	1		Near Montara, at south of 9th Street. Repair damaged	2028H	0Q670	201.131	22/23	\$418	\$0	\$415	\$1,808	\$0	\$418	\$388	\$27	\$373	\$35	\$1,400	\$2,641
				storm drain and restore eroded embankment.						·					·	·	·	·	. ,	. ,
04	SM	84		Near La Honda, west of Peek-A-Boo Lane. Construct	1455C	2K640	201.131	22/23	\$1,056	\$675	\$0	\$4,057	\$0	\$1,056	\$635	\$40	\$484	\$371	\$3,202	\$5,788
				soldier pile wall, reconstruct damaged pavement, and					. ,	·				. ,	·	·	·		. ,	. ,
				upgrade guardrail.																
04	SM	84		Near La Honda, at 0.5 mile west of Pescadero Creek	2032A	0Q480	201.131	22/23	\$924	\$0	\$809	\$4,762	\$0	\$924	\$809	\$33	\$522	\$146	\$4,061	\$6,495
				Road. Repair slope washout by constructing a retaining						·						·		·		,
				wall.																
04	SOL	505		Near Vacaville, at southbound offramp to Allendale	2021G	0Q710	201.131	22/23	\$317	\$0	\$427	\$1,276	\$0	\$317	\$402	\$25	\$385	\$50	\$841	\$2,020
				Road. Restore slope washout between offramp and	1												,			
				adjacent frontage road by placing rock slope protection.																
				, , , , , , , , , , , , , , , , , , , ,																
04	SON	116		Near Monte Rio, at 0.2 mile west of Cnopius Road.	1464F	2K360	201.131	22/23	\$1,775	\$0	\$2,087	\$7,805	\$0	\$1.775	\$1,883	\$204	\$1,441	\$384	\$5,980	\$11,667
0-					1	1		1	, ,		, ,	, , , , , ,		, ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1	, ,		, , ,	, , ,
0-1				Repair unstable slope by constructing a retaining wall.																

April 28, 2021 3 of 4

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

NAP 121 9.7/10.3 Near Schellville, from 0.2 mile to 0.8 mile north of Ramal Road. Restore structural integrity of the existing roadway by injecting polyurethane to densify the soil below and minimizing future settlement, grind and replace asphalts concrete, and rehabilitate drainage systems. 121 13.4/20.7 Nor Napa, from 2.8 miles north of Vichy Avenue to 1.4 miles south of Route 128 at various locations. Repair and restore slope washouts with Rock Slope Protection (RSP), erosino control, steel sheet piles, and drainage upgrades. 152 20.5/20.8 Near Calistoga, at 2.5 miles east to 1.1 miles east of San Felipe Road. Stabilize slome damaged embankment. 2022H 0.0830 201.131 23/24 50 \$7.36 \$1.003 \$0 \$2.323 \$7.36 \$885 \$118 \$878 \$165 \$1.25	Φ0.040
Indicating polyurethane to densify the soil below and minimizing future settlement, grind and replace asphalt concrete, and rehabilitate drainage systems. 2022D	\$6,219
below and minimizing future settlement, grind and replace asphalt concrete, and rehabilitate drainage systems.	
replace asphalt concrete, and rehabilitate drainage systems. 04 NAP 121 13.4/20.7 Near Napa, from 2.8 miles north of Vichy Avenue to 1.4 miles south of Route 128 at various locations. Repair and restore slope washouts with Rock Slope Protection (RSP), erosion control, steel sheet piles, and drainage upgrades. 04 NAP 29 Near Calistoga, at 2.5 miles south of Lake County line. Stabilize storm damaged embankment. 04 SCL 152 20.5/20.8 Near Gilroy, from 0.8 mile east to 1.1 miles east of San Felipe Road. Stabilize slope with Rock Slope Protection (RSP), erosion control, and drainage upgrades. 04 SON 116 Near Jenner, at 1.1 miles east of Route 1. Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP). 05 SM 84 Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushons and guardrali.	
Systems.	
NAP 121 13.4/20.7 Near Napa, from 2.8 miles north of Vichy Avenue to 1.4 miles south of Route 128 at various locations. Repair and restore slope washoust with Rock Slope Protection (RSP), erosion control, steel sheet piles, and drainage upgrades. Near Calistoga, at 2.5 miles south of Lake County line. Stabilize storm damaged embankment. 2022H 0Q830 201.131 23/24 \$0 \$736 \$1,003 \$0 \$2,323 \$736 \$885 \$118 \$878 \$165 \$1,203 \$1,003 \$0 \$2,323 \$736 \$885 \$118 \$878 \$165 \$1,203 \$1,003 \$1,	
1.4 miles south of Route 128 at various locations. Repair and restore slope washouts with Rock Slope Protection (RSP), erosion control, steel sheet piles, and drainage upgrades.	
Repair and restore slope washouts with Rock Slope Protection (RSP), erosion control, steel sheet piles, and drainage upgrades.	\$10,191
Protection (RSP), erosion control, steel sheet piles, and drainage upgrades.	
and drainage upgrades. 04 NAP 29	
NAP 29 Near Calistoga, at 2.5 miles south of Lake County line. 2022H 0Q830 201.131 23/24 \$0 \$736 \$1,003 \$0 \$2,323 \$736 \$885 \$118 \$878 \$165 \$1,205 \$1,205 \$2,005	
Stabilize storm damaged embankment. O4 SCL 152 20.5/20.8 Near Gilroy, from 0.8 mile east to 1.1 miles east of San Felipe Road. Stabilize slope with Rock Slope Protection (RSP), erosion control, and drainage upgrades. O4 SON 116 Near Jenner, at 1.1 miles east of Route 1. Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP). O5 SM 84 Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	
SCL 152 20.5/20.8 Near Gilroy, from 0.8 mile east to 1.1 miles east of San Felipe Road. Stabilize slope with Rock Slope Protection (RSP), erosion control, and drainage upgrades. Solution	\$4,062
San Felipe Road. Stabilize slope with Rock Slope Protection (RSP), erosion control, and drainage upgrades. O4 SON 116 Near Jenner, at 1.1 miles east of Route 1. Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP). O4 SM 84 Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail. San Felipe Road. Stabilize slope with Rock Slope Protection (RSP), and shall crash cushions and guardrail. San Felipe Road. Stabilize slope with Rock Slope Protection (RSP), and shall construct retaining wall, and install crash cushions and guardrail.	
Protection (RSP), erosion control, and drainage upgrades. O4 SON 116 Near Jenner, at 1.1 miles east of Route 1. Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP). O4 SM 84 Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	\$3,409
upgrades. Near Jenner, at 1.1 miles east of Route 1. Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP). Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	
Near Jenner, at 1.1 miles east of Route 1. Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP). Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	
Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP). Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	
culvert wingwalls and placing Rock Slope Protection (RSP). Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	\$6,029
Protection (RSP). Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	
Near Woodside, at 1.1 miles south of Portola Road. Repair slipout, construct retaining wall, and install crash cushions and guardrail.	
Repair slipout, construct retaining wall, and install crash cushions and guardrail.	
crash cushions and guardrail.	\$4,130
04 ISON 1 15.1/15.7 Near Carmet, from 0.1 mile to 0.7 mile north of Calle 0748R 0A021 201.131	40.100
	\$8,400
Del Sol. Biological mitigation for project EA 0A020.	
04 SON 1 15.1/15.7 Near Carmet, from 0.1 mile to 0.7 mile north of Calle 0748S 0A022 201.131 \$1,000 \$0 \$200 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$1,000 \$0	\$1,200
Del Sol. Stormwater mitigation for project EA	
0A020.	
2020 SHOPP - Emergency Response TOTAL \$46,212 \$152,242 \$46,747 \$33,050 \$14,991 \$19,606 \$24,128 \$2,969 \$43,096 \$27,724 \$175,7	
SHOPP - Emergency Response NEW REQUESTED TOTAL \$52,540 \$152,242 \$46,747 \$33,050 \$14,991 \$20,833 \$25,628 \$3,147 \$44,336 \$27,905 \$177,7	•
SHOPP - ER PROGRAMMED TOTAL \$44,540 \$82,056 \$41,842 \$27,377 \$2,323 \$16,583 \$20,422 \$2,361 \$23,801 \$17,795 \$117,7	6 \$198,138
SHOPP - ER DIFFERENCE TOTAL \$8,000 \$70,186 \$4,905 \$5,673 \$12,668 \$4,250 \$5,206 \$786 \$20,535 \$10,110 \$60,5	\$101,432

April 28, 2021 4 of 4