GL: Emergency Relief – SHOPP Emergency Response Program (TIP ID – VAR170008)

Last updated with TIP Revision 2021-19

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Co	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	MRN			Near Sausalito, at 0.1 mile south of Alexander Avenue.	1492J	4J420		19/20	\$3,559	\$0	\$0	\$0	\$0	\$837	\$850	\$100	\$850	\$13	\$909	\$3,559
				Restore damaged drainage systems.																
04	SM	280	20.3/20.	In San Bruno, from Jenevein Avenue to 0.1 mile south	1499H	4J080	201.131	19/20	\$2,769	\$0	\$0	\$0	\$0	\$390	\$650	\$78	\$390	\$168	\$1,093	\$2,769
				of San Bruno Avenue. Reconstruct failed concrete																
				ditch and place Rock Slope Protection (RSP) at slope																
				washouts as storm damage permanent restoration.																
							F	T-4-1	***	**	**	00	00	#4.007	#4 500	0.470	04.040	\$404	***	***
04	ALA	000		In Hayward, at Industrial Parkwal Overcrossing No.33-	Lagnad	1W210	ime Extensi 201.130	20/21	\$6,328 \$0	\$0 \$2,800	\$0 \$0	\$0 \$0	\$0	\$1,227 \$0	\$1,500 \$0	\$178 \$0	\$1,240 \$800	\$181 \$0	\$2,002 \$2,000	\$6,328 \$2,800
04	ALA	000		0398. Repair bridge by replacing exterior girder,	2004P	100210	201.130	20/21	ΦО	φ2,000	ΦΟ	\$0	φU	φU	ΦU	Φυ	φουυ	ΦU	\$2,000	\$2,000
				adjoining deck, and barrier rail, and install advanced																
				warning signs.																
04	ALA	580		In Oakland, at Harrison Street Undercrossing No. 33-	2906M	1W540	201.130	20/21	\$0	\$1,190	\$0	\$0	\$0	\$0	\$0	\$0	\$270	\$20	\$900	\$1,190
04	/\L/\	300		0289S. Construct wrought iron fencing with secured	2500101	1000-0	201.100	20/21	ΨΟ	ψ1,100	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΖΙΟ	ΨΖΟ	ΨΟΟΟ	ψ1,130
				access gates.																
04	ALA	880		In Oakland, at 16th Avenue Overcrossing No. 33-0137.	2907F	1W420	201.130	20/21	\$0	\$565	\$0	\$0	\$0	\$0	\$0	\$0	\$155	\$0	\$410	\$565
•				Repair spalled surfaces on the soffit, secure soffit					4.0	4000	**	, , , , , , , , , , , , , , , , , , ,	, ,	,	ų.	4.0	Ψ.00	Ψū	4	4000
				access, and clear out the burned material.																
04	ALA	80	5.7/5.8	,	2908N	1W990	201.130	20/21	\$0	\$3,600	\$0	\$0	\$0	\$0	\$0	\$50	\$950	\$50	\$2,550	\$3,600
				Frontage Road onramp and offramp (PM 4.6).						. ,						·	·		. ,	. ,
				Construct wrought iron fencing with secured access																
				gates.																
04	ALA	880	34.2/34.	6 In Oakland, along Wood Street between 14th Street	2908G	2W340	201.130	20/21	\$0	\$3,869	\$0	\$0	\$0	\$0	\$0	\$50	\$1,150	\$50	\$2,619	\$3,869
				and West Grand Avenue. Clear the area of debris and																
				hazardous material, remove abandoned vehicles,																
				restore drainage, regrade, and construct fencing with																
				secured access gates.																
04	CC	4		In Pittsburg, at 0.4 mile east of Harbor Street. Replace	2909C	2W670	201.130	20/21	\$0	\$1,350	\$0	\$0	\$0	\$0	\$0	\$20	\$400	\$0	\$930	\$1,350
				damaged culverts, backfill eroded areas, replace																
				irrigation system, and install erosion control.																
04	CC	24	6.6/7.4	In Lafayette, on westbound Route 24, from 1.1 miles	2907H	0W610	201.130	20/21	\$0	\$1,260	\$0	\$0	\$0	\$0	\$0	\$20	\$280	\$20	\$940	\$1,260
				west to 0.3 mile west of Pleasant Hill Road																
				Undercrossing. Repair settlement by injecting																
				polyurthane and grout in voids, replace culverts, and																
0.4	MON	4	40 7/44	repair pavement. Near Stinson Beach, from 1.5 miles south to 1.2 miles	20220	0AA48	004 404	00/04	CO44	Φ4 400	Φ0	Φ0	Φ0	Φ0	#007	CO 4	# 000	CO4	#4.400	Φ4 040
04	MRN	1	10.7/11.	,	2032Q	UAA48	201.131	20/21	\$311	\$1,499	\$0	\$0	\$0	\$0	\$227	\$84	\$336	\$31	\$1,132	\$1,810
				south of Panoramic Highway North. Four-year																
				mitigation plant establishment and monitoring for emergency projects EA 4K240 and EA 4S220.																
Ω4	MDN	101	3.5/4.8		2007	1W580	201.130	20/21	\$0	\$1,040	\$0	\$0	\$0	\$0	\$0	\$0	\$260	\$0	\$780	\$1,040
U -1	IVIIXIN	101	5.5/4.0	Richardson Bay Bridge and Separation No. 27-0010.	29013	1 4 4 3 6 6	201.130	20/21	ΨΟ	ψ1,040	ΨΟ	ΨΟ	ΨΟ	Ψυ	Ψυ	ΨΟ	ΨΖΟΟ	ψυ	ΨΙΟΟ	ψ1,040
				Repair expansion joints.																
04	MRN	1		Near Five Brooks, at Giacomini Creek Bridge No. 27-	2032F	0AA44	201.131	20/21	\$453	\$1,513	\$0	\$0	\$0	\$0	\$400	\$53	\$650	\$15	\$848	\$1,966
	```			0122. Four-year mitigation plant establishment for					, .55	÷ .,• .•		+ -	<b>,</b>	<b>,</b>	÷ .50	755	, 555	7.0	, 0.0	+ .,500
				emergency project EA 4K850.																
04	NAP	29	42.1/48.	Near Calistoga, from 2.6 miles north of Tubbs Lane to	0379T	2W760	201.130	20/21	\$0	\$6,050	\$0	\$0	\$0	\$0	\$0	\$50	\$1,500	\$0	\$4,500	\$6,050
				Lake County line. Repair damaged roadway by grinding																
				and overlaying with rubberized asphalt.																
04	NAP	29	33.5/48.	In and near Calistoga, from Lakemead Lane to Lake	2907B	1W630	201.130	20/21	\$0	\$5,320	\$0	\$0	\$0	\$0	\$0	\$20	\$1,200	\$100	\$4,000	\$5,320
				County line; also in and near Santa Rosa in Sonoma																
				County on Route 12, from 0.1 mile east of Acacia Lane																
				to Hoff Road (PM 19.3/25.8). Repair or replace																
				guardrails, ditches, signs, fencing, drainage and																
				electrical facilities, remove debris and hazardous trees,																
				repair pavement, and install erosion control in fire																
				damaged areas.																
		1			1			I												

April 27, 2022 1 of 5

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
	NAP			In Napa and Solano Counties on Routes 121 and 128		1W480		20/21	\$0	\$10,420	\$0	\$0	\$0	\$0	\$0	\$0	\$2,400	\$20	\$8,000	\$10,420
				at various locations. Repair culverts, retaining walls,						. ,	·			·	·		. ,		. ,	. ,
				and pavement, remove hazardous trees, replace																
				guardrails, and install erosion control in fire damaged																
				areas.									* -							
04	SCL	35		Near Los Gatos, at 1.8 miles north of Black Road.	2035F	0W170	201.130	20/21	\$0	\$1,700	\$0	\$0	\$0	\$0	\$0	\$0	\$400	\$0	\$1,300	\$1,700
04	001	400	44 0/00 /	Stabilize slope and improve drainage systems.	00000	414/000	004.400	00/04	Φ0	ФС 040	<b>#</b> 0	Φ0	Φ0	Φ0	Φ0	<b>#</b> 00	Φ4 Ω <b>Γ</b> Ω	<b>#400</b>	<b>#4.500</b>	ФС 040
04	SCL	130	11.2/22.5	Near San Jose, from Quimby Road to Observatory Peak Road. Repair damaged culverts and pavement,	2906N	1W620	201.130	20/21	\$0	\$6,010	\$0	\$0	\$0	\$0	\$0	\$60	\$1,350	\$100	\$4,500	\$6,010
				replace signs and delineators, and install erosion																
				control in fire damaged areas.																
04	SCL	130	15.0/21.5	Near San Jose, from 0.8 mile west of Smith Creek	2906D	1W510	201.130	20/21	\$0	\$2,720	\$0	\$0	\$0	\$0	\$0	\$20	\$600	\$100	\$2,000	\$2,720
				Bridge to 1.0 mile west of Observatory Peak Road.						,							·	·		,
				Repair or replace guardrails, signs, ditches, drainage																
				and electrical facilities, remove debris and hazardous																
				trees, and install erosion control in fire damaged areas.																
04	SCL	101		In Mountain View, at North Shoreline Boulevard onramp	2804C	0W680	201.130	20/21	\$0	\$770	\$0	\$0	\$0	\$0	\$0	\$0	\$200	\$0	\$570	\$770
				to southbound Route 101. Replace culverts, inject	200.0		2011100	20,21	Ψ.	ψσ	Ψ		Ψ**	Ψ.	Ψ		ΨΞοσ	Ψ	ΨΟΙΟ	Ψ
				polyurethane foam, and reconstruct pavement.																
04	SCL	280		In Cupertino, at Calabazas Creek Bridge No. 37-0405.	2908B	0W420	201.130	20/21	\$0	\$1,155	\$0	\$0	\$0	\$0	\$0	\$0	\$270	\$0	\$885	\$1,155
				Stabilize and lift concrete slabs by performing																
				polyurethane injection and replace damaged concrete																
04	SCL	101		slabs.  Near Gilroy, at Sargent Bridge and Overhead No. 39-	14E2D	4J030	201.131	20/21	\$1,482	\$3,090	\$0	\$0	\$0	\$650	\$780	\$52	\$900	\$87	\$2,103	\$4,572
04	SCL	101		0006L. Permanent restoration of roadway settlement	14336	43030	201.131	20/21	φ1,402	φ3,090	φυ	φυ	φυ	φυσυ	Φ/ Ο Ο	φ52	φθυσ	φοι	φ <u>2,103</u>	φ4,37 <i>2</i>
				and southern abutment wingwall movement.																
				g																
04	SCL	101		In San Jose, at 0.2 mile north of Tully Road. Replace	2908K	2W390	201.130	20/21	\$0	\$2,070	\$0	\$0	\$0	\$0	\$0	\$20	\$550	\$0	\$1,500	\$2,070
				failed culvert, backfill eroded areas, replace irrigation																
				system, and install erosion control.																
04	SF	101		In the City and County of San Francisco, at Central	2907M	1W980	201.130	20/21	\$0	\$1,090	\$0	\$0	\$0	\$0	\$0	\$10	\$270	\$0	\$810	\$1,090
				Viaduct No. 34-0077. Replace the damaged concrete																
04	SM	1	0 0/13 5	barrier and guardrail.  Near Pescadero, from Santa Cruz County line to	20065	1\//520	201.130	20/21	\$0	\$1,080	\$0	\$0	\$0	\$0	\$0	\$20	\$260	\$50	\$750	\$1,080
04	Sivi	' '	0.0/13.3	Pescadero Creek Road. Repair or replace guardrails,	2900L	100320	201.130	20/21	ΨΟ	φ1,000	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΖΟ	ΨΖΟΟ	φου	Ψίσο	φ1,000
				signs, ditches, drainage and electrical facilities, remove																
				debris and hazardous trees, and install erosion control																
				in fire damaged areas.																
04	SM	82		In South San Francisco, at 0.1 mile north of Francisco	1450J	0K670	201.131	20/21	\$1,270	\$3,806	\$0	\$0	\$0	\$500	\$710	\$60	\$800	\$27	\$2,979	\$5,076
				Drive. Permanent embankment restoration by installing																
				retaining wall and drainage improvements.																
04	SM	2/		Near Woodside, at 1.1 miles south of Portola Road.	20070	0W120	201.130	20/21	\$0	\$4,130	\$0	\$0	\$0	\$0	\$210	\$20	\$900	\$0	\$3,000	\$4,130
04	SIVI	04		Repair slipout, construct retaining wall, and install crash		000120	201.130	20/21	φυ	ψ4, 130	φυ	φυ	φυ	φυ	ψ∠ 10	φΖΟ	φθυυ	φυ	ψ3,000	ψ4,130
				cushions and guardrail.																
04	SM	101		In Milipitas, at Henderson Underpass. Install new drain	2908D	2W310	201.130	20/21	\$0	\$1,430	\$0	\$0	\$0	\$0	\$0	\$30	\$320	\$80	\$1,000	\$1,430
				pipe, erosion control, and Rock Slope Protection (RSP),																
				and replace chainlink fence and concrete barrier.																
6.1	00:			N	0004:	0)4/505	004.400	00/0/	Φ.0	Φ.Ε.Ο.Ο.	Φ.2	<b>#</b> 2	# 0	<b>#</b> 0	Φ.	# 0	<b>0.4</b> = 0	0.0	<b>#</b> 400	<b>#</b> 500
04	SOL	37		Near Vallejo, at the Route 37/29 Separation No. 23-	2904J	0W580	201.130	20/21	\$0	\$582	\$0	\$0	\$0	\$0	\$0	\$0	\$152	\$0	\$430	\$582
				0218. Replace expansion joint system.		l .														

April 27, 2022 2 of 5

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	SOL	80	20.9/25	In and near Fairfield and Vacaville, from North Texas	2905E	1W490	201.130	20/21	\$0	\$3,290	\$0	\$0	\$0	\$0	\$0	\$0	\$750	\$40	\$2,500	\$3,290
				Street to Alamo Drive. Repair or replace guardrails,																
				ditches, drainage and electrical facilities, signs and																
				fencing, replace oleanders in the median, remove																
				debris and hazardous trees, and install erosion control																
				in fire damaged areas.																
04	SON	1		Near Jenner, at 0.3 mile north of Pacific View Drive.	2906K	1W550	201.130	20/21	\$0	\$600	\$0	\$0	\$0	\$0	\$0	\$0	\$150	\$0	\$450	\$600
				Construct sheet pile retaining wall, stabilize slope with																
				Rock Slope Protection (RSP), replace culvert, and																
				reconstruct roadway.																
04	SON	1	27.3/31		2906B	1W500	201.130	20/21	\$0	\$20,890	\$0	\$0	\$0	\$0	\$0	\$60	\$4,750	\$80	\$16,000	\$20,890
				Road to 1.5 miles south of Fort Ross Road. Repair or																
				replace guardrails, drainage systems, electrical																
				facilities, signs and fencing, repair damaged retaining																
				walls, remove debris and hazardous trees, and install																
0.4	001	400	40.0/47	erosion control in fire damaged areas.	00005	0)4/000	004.400	00/04	Φ0	#0.0F0	Φ0	Φ0	00	00	Φ0	Φ.Ε.Ο.	0.450	Φ.Ε.Ο.	Φ4 F00	Φ0.050
04	SON	128	16.8/17	6 Near Healdsburg, from 0.4 mile west to 0.4 mile east of	2908E	200330	201.130	20/21	\$0	\$2,050	\$0	\$0	\$0	\$0	\$0	\$50	\$450	\$50	\$1,500	\$2,050
				Maacama Creek Bridge. Stabilize slope, improve																
				drainage, install underdrains, remove debris and loose																
				rock, and install Rock Slope Protection (RSP) and erosion control.																
04	SON	1	15 1/15	7 Near Carmet, from 0.1 mile to 0.7 mile north of Calle	07/8E	0A020	201.131	20/21	\$17,698	\$40,824	\$0	\$0	\$0	\$0	\$1,800	\$500	\$5,000	\$15 308	\$35,824	\$58,522
04	OON	'	13.1/13.	Del Sol. Realign roadway near Gleason Beach.	0740L	0/10/20	201.131	20/21	ψ17,030	ψ+0,02+	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ψ1,000	ψυσο	ψ5,000	ψ10,000	ψ55,024	Ψ30,322
04	SON	1	26 7/27	Near Jenner, from 0.3 to 0.4 mile north of Myers Grade	0482T	0J300	201.131	20/21	\$4,810	\$19,100	\$0	\$0	\$0	\$2,106	\$2,496	\$208	\$3,137	\$243	\$15,720	\$23,910
04	OON	'	20.1121	Road. Permanent restoration of roadway slipouts.	04021	00000	201.131	20/21	ψ4,010	φ13,100	ΨΟ	ΨΟ	ΨΟ	ψ2,100	ψ2,430	ΨΖΟΟ	φ3,137	ΨΖΨΟ	φ13,720	Ψ23,310
				Trodu. 1 cimanoni restoration or roadway supodis.																
04	SON	101		Near Petaluma, north of Pepper Road. Environmental	0481G	0.1101	201.131	20/21	\$0	\$140	\$0	\$0	\$0	\$0	\$0	\$0	\$140	\$0	\$0	\$140
0.	00.1			mitigation for project EA 0J100.	01010	00101	201.101	20/21	ΨΟ	Ψιισ	ΨΟ	ΨΟ	ΨΟ	Ψ"	ΨΟ	ΨΟ	Ψ110	Ψ	Ψ σ	Ψιισ
04	ALA	680		In Fremont, at the northbound offramp to Mission	2028M	0Q680	201.131	21/22	\$750	\$945	\$3,946	\$0	\$0	\$750	\$885	\$60	\$1,033	\$5	\$2,908	\$5,641
				Boulevard. Stabilize storm damaged embankment.					ψ. σσ	Ψ	40,010	4.0	4.0	4.00	<b>4000</b>	, , ,	4 1,000	<b>,</b>	4_,000	40,0
04	ALA	92		In Hayward, at the westbound connector from	2028K	0Q450	201.131	21/22	\$285	\$363	\$862	\$0	\$0	\$285	\$347	\$16	\$191	\$10	\$661	\$1,510
				northbound Route 880. Restore eroded embankment					,	,	,	•	, -	,	• -	, -	, ,	, -	,	* ,
				and extend existing concrete barrier.																
04	ALA	260	1.1/1.9		2909B	2W740	201.131	21/22	\$0	\$0	\$8,550	\$0	\$0	\$0	\$0	\$0	\$2,050	\$0	\$6,500	\$8,550
				Tube No. 33-0106R (PM R1.1R to R1.9R) and Webster																
				Tube No. 33-0106L (PM R1.1L to R1.9L). Install fuel																
				cell power supply systems to maintain safety systems in																
				the event of a fire emergency.																
04	CC	80		Near San Pablo, on El Portal Drive onramp to	2909P	3W770	201.130	21/22	\$0	\$0	\$815	\$0	\$0	\$0	\$0	\$10	\$270	\$10	\$525	\$815
				westbound Route 80. Reconstruct the damaged																
		<u> </u>		soundwall and concrete barrier.	ļ.,			L												
04	MRN	101	3.5/4.7	Near Sausalito, at Richardson Bay Bridge No. 27-0010.	2909E	3W390	201.130	21/22	\$0	\$0	\$935	\$0	\$0	\$0	\$0	\$0	\$325	\$0	\$610	\$935
				Remove damaged expansion joint, repair concrete																
		1		section, and install new finger joints.	000.	010115	00115	0.15-		A 1==	<b>A</b> ( <b>A</b> :=		4.5	4.5	<b>*</b> * * * * *		A		<b>A</b> ( <b>3</b> ) )	00.00
04	MRN	1		Near Stinson Beach, at 0.7 mile south of Panoramic	2034J	0W130	201.131	21/22	\$0	\$479	\$1,845	\$0	\$0	\$0	\$454	\$25	\$500	\$31	\$1,314	\$2,324
				Highway. Implement permit requirements including																
				plant establishment, noxious weed control, seed																
				collection and propagation, and biological monitoring for																
0.4	NIAD	20	11 6/10	emergency project EA 0P130.	2022	00000	204 424	24/22	¢4.407	<b>#</b> O	¢16 610	ΦO	<b>C</b> O	¢4.407	¢4.700	¢450	#4 000	<b>C</b> 4 4	¢42.400	¢40.050
04	INAP	29	11.6/13	O In Napa, from First Street to 0.1 mile south of Redwood	2022G	UQ820	201.131	21/22	\$1,437	\$0	\$16,619	\$0	\$0	\$1,437	\$1,792	\$152	\$1,228	\$44	\$13,403	\$18,056
0.4	VIV D	10	2 4/2 0	Road/Trancas Street. Repair culvert.	20245	00600	204 424	24/22	¢200	¢470	¢4.770	ΦO	<b>C</b> C	¢200	¢220	¢450	¢400	¢424	¢4 045	¢0 557
04	NAP	12	2.1/2.6		2021F	04690	201.131	21/22	\$308	\$470	\$1,779	\$0	\$0	\$308	\$320	\$150	\$400	\$134	\$1,245	\$2,557
				the Solano County line. Repair storm damaged slopes																
				at two locations with Rock Slope Protection (RSP) and																
		1		restore ditches.	<u> </u>	<u> </u>		<u> </u>												

April 27, 2022 3 of 5

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	SCL	152	10.2/10.4	In Gilroy, from Route 101 to Camino Arroyo.	2910B	3W840		21/22	\$0	\$0	\$790	\$0	\$0	\$0	\$0	\$0	\$260	\$0	\$530	\$790
				Reconstruct damaged pavement, repair light pole, sign					·	·						·				
				posts, and landscaping, clean drainage system, and																
				remove hazardous waste.																
04	SCL	9		In Saratoga, north of Pierce Road (PM 5.97). Install	1464D	2K280	201.131	21/22	\$484	\$0	\$1,589	\$0	\$0	\$130	\$318	\$36	\$315	\$10	\$1,264	\$2,073
				Rock Slope Protection (RSP) and replace culvert.	4.45011	01/570	004.404	0.1/0.0	4770	40	<b>*</b> 4 4 4 4 0 0		**	****	<b>*</b> 400	470	4500	40	***	***
04	SM	1		Near Half Moon Bay, at 1.1 miles north of Santa Cruz	1450H	0K570	201.131	21/22	\$770	\$0	\$1,492	\$0	\$0	\$300	\$400	\$70	\$500	\$2	\$990	\$2,262
				County line. Repair slope washout by constructing a																
				soldier pile wall and upgrading the drainage system.																
04	SM	84		Near La Honda, at 1.2 miles north of Madera Lane	1455B	2K610	201.131	21/22	\$936	\$400	\$4,047	\$0	\$0	\$936	\$390	\$10	\$750	\$30	\$3,267	\$5,383
Ŭ.	Oivi	`		(north). Repair slope washout and place Rock Slope	11005	211010	201.101	- 1/22	φοσσ	Ψ100	Ψ1,017	Ψ	Ψο	Ψοσο	Ψοσο	Ψισ	Ψίου	ΨΟΟ	ψ0,201	ψ0,000
				Protection (RSP) on existing embankment to prevent																
				further erosion.																
04	SON	101		Near Cloverdale, at 0.4 mile south of the Mendocino	1462P	2K350	201.131	21/22	\$840	\$541	\$3,304	\$0	\$0	\$840	\$413	\$128	\$459	\$225	\$2,620	\$4,685
				County line. Restore slope, rebuild damaged gutter																
				and install erosion control measures.								* -								
04	SON	1	15.1/15.7	Near Carmet, from 0.1 mile to 0.7 mile north of Calle	0748R	0A021	201.131	21/22	\$7,000	\$0	\$1,400	\$0	\$0	\$0	\$0	\$0	\$1,400	\$7,000	\$0	\$8,400
04	SON	1	15 1/15 7	Del Sol. Biological mitigation for project EA 0A020.  Near Carmet, from 0.1 mile to 0.7 mile north of Calle	07400	0A022	201.131	24/22	¢4 000	¢Λ	\$200	<b></b>	¢o.	<b>C</b> O	ΦO	¢Ω	#200	¢4.000	¢Λ	¢4 200
04	20N	'	15.1/15.7	Del Sol. Stormwater mitigation for project EA 0A020.	07485	UAU22	201.131	21/22	\$1,000	\$0	\$200	\$0	\$0	\$0	\$0	\$0	\$200	\$1,000	\$0	\$1,200
				Del 301. Storriwater mitigation for project EA 0A020.																
04	ALA	580		Near Livermore, at 0.3 mile west of Stonecut	1461D	0P120	201.131	22/23	\$752	\$0	\$1,467	\$4,930	\$0	\$752	\$1,362	\$105	\$1,270	\$70	\$3,590	\$7,149
•				Underpass (PM R4.3L). Restore eroded embankment				,_	Ų. U <u></u>	ų v	<b>4</b> .,	4 .,	4.5	4.02	4 1,002	ψ	<b>V</b> .,=. <b>V</b>	4.5	ψο,σσσ	Ψ.,
				slope in the eastbound direction and install erosion																
				control measures.																
04	CC	680	19.2/19.9	In Concord and Pleasant Hill, at Willow Pass Road	2028N	0Q780	201.131	22/23	\$608	\$0	\$818	\$2,950	\$0	\$608	\$752	\$66	\$807	\$24	\$2,119	\$4,376
				Undercrossing No. 28-0178 and Concord Avenue																
				Undercrossing No. 28-0190. Stabilize storm damaged																
0.4	NIAD	404	40.0/40.4	abutment slopes by paving with concrete.	00005	00040	004.404	00/00	Φ0	<b>#</b> 000	M4 400	Φ0.000	00	0000	Φ4.007	<b>0470</b>	0004	Φ00	<b>04.040</b>	<b>#</b> 4.400
04	NAP	121	16.0/16.1	Near Napa, at Wooden Valley Road. Repair pavement, replace drainage systems, and upgrade guardrail.	2022F	0Q810	201.131	22/23	\$0	\$902	\$1,460	\$2,060	\$0	\$902	\$1,287	\$173	\$661	\$86	\$1,313	\$4,422
				replace drainage systems, and upgrade guardiali.																
04	SM	1		Near Montara, at south of 9th Street. Repair damaged	2028H	0Q670	201.131	22/23	\$418	\$0	\$415	\$1,808	\$0	\$418	\$388	\$27	\$373	\$35	\$1,400	\$2,641
0.	0			storm drain and restore eroded embankment.	202011	000.0	2011101		Ψίιο	ΨΟ	<b>V</b>	ψ1,000	Ψ.	<b>V</b>	Ψοσο	Ψ2.	Ψοισ	Ψ00	Ψ1,100	Ψ=,σ
04	SM	84		Near La Honda, west of Peek-A-Boo Lane. Construct	1455C	2K640	201.131	22/23	\$1,056	\$675	\$0	\$4,057	\$0	\$1,056	\$635	\$40	\$484	\$371	\$3,202	\$5,788
				soldier pile wall, reconstruct damaged pavement, and																
				upgrade guardrail.																
04	SM	84		Near La Honda, at 0.5 mile west of Pescadero Creek		0Q480	201.131	22/23	\$924	\$0	\$809	\$4,762	\$0	\$924	\$809	\$33	\$522	\$146	\$4,061	\$6,495
				Road. Repair slope washout by constructing a retaining																
04	SOL	505		wall.  Near Vacaville, at southbound offramp to Allendale	20216	0Q710	201.131	22/23	\$317	\$0	\$500	\$1,276	\$0	\$317	\$402	\$98	\$385	\$50	\$841	\$2,093
04	SUL	303		Road. Restore slope washout between offramp and	20216	100/10	201.131	22/23	φ317	φυ	φ300	φ1,270	φυ	φοιτ	<b>Φ402</b>	φ90	φοου	φου	<b>Ф</b> 04 I	φ <b>2</b> ,093
				adjacent frontage road by placing rock slope protection.																
				pagason nomage road by placing rook clope protocion.																
04	SON	116		Near Monte Rio, at 0.2 mile west of Cnopius Road.	1464F	2K360	201.131	22/23	\$1,775	\$0	\$2,087	\$7,805	\$0	\$1,775	\$1,883	\$204	\$0	\$384	\$0	\$4,246
				Repair unstable slope by constructing a retaining wall.					, ,	* -	, , , , , ,	, , ,	, -	, , -	, ,	,	, ,	,	***	. , -
				(G13 Contingency)																
04	SON	121	9.7/10.3	Near Schellville, from 0.2 mile to 0.8 mile north of		4K140	201.131	22/23	\$528	\$972	\$0	\$4,719	\$0	\$528	\$941	\$31	\$668	\$11	\$4,040	\$6,219
				Ramal Road. Restore structural integrity of the existing																
				roadway by injecting polyurethane to densify the soil																
				below and minimizing future settlement, grind and																
				replace asphalt concrete, and rehabilitate drainage																
				systems.			<u> </u>													

April 27, 2022 4 of 5

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	F	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	<b>RW SUP</b>	CONSUP	RW	CON	TOTAL
	NAP		13.4	;	Near Napa, from 2.8 miles north of Vichy Avenue to 1.4 miles south of Route 128 at various locations. Repair and restore slope washouts with Rock Slope Protection (RSP), erosion control, steel sheet piles, and drainage upgrades.	2022D	0Q790	201.131	23/24	\$0	\$1,635	\$0	\$2,252	\$6,304	\$1,635	\$2,053	\$199	\$1,361	\$639	\$4,304	\$10,191
04	NAP	29			Near Calistoga, at 2.5 miles south of Lake County line. Stabilize storm damaged embankment.	2022H	0Q830	201.131	23/24	\$0	\$736	\$1,003	\$0	\$2,323	\$736	\$885	\$118	\$878	\$165	\$1,280	\$4,062
04	SCL	152	20.5		Near Gilroy, from 0.8 mile east to 1.1 miles east of San Felipe Road. Stabilize slope with Rock Slope Protection (RSP), erosion control, and drainage upgrades.	2031M	3Q650	201.131	23/24	\$0	\$583	\$0	\$581	\$2,245	\$583	\$492	\$89	\$556	\$168	\$1,521	\$3,409
04	SON	116		ı	Near Jenner, at 1.1 miles east of Route 1. Permanent restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP).	2031S	0AA63	201.131	23/24	\$0	\$1,130	\$0	\$780	\$4,119	\$1,130	\$710	\$70	\$710	\$656	\$2,753	\$6,029
04	SON	1	26.7	(	Near Jenner, from 0.3 to 0.7 mile north of Myers Grade Road. Mitigation project for EA 0J300 for plant establishment and erosion control.	2911P	0J301	201.131	23/24	\$0	\$0	\$0	\$1,010	\$5,972	\$0	\$1,000	\$10	\$2,800	\$0	\$3,172	\$6,982
04	MRN	1			Near Muir Beach, at 0.6 mile south of Pacific Way. Repair and extend retaining wall, replace culvert and guardrail, and repair pavement.	2906H	3AA50	201.131	25/26	\$1,054	\$0	\$0	\$0	\$1,934	\$1,054	\$1,729	\$205	\$0	\$0	\$0	\$2,988
04	MRN	101	6.1	1/6.3	In Corte Madera, from 0.4 mile to 0.6 mile north of Route 131 (Tiburon Boulevard). Restore slope, regrade unlined ditch, and install erosion control measures.	2032M	2AA30	201.131	25/26	\$714	\$0	\$0	\$0	\$993	\$714	\$964	\$29	\$0	\$0	\$0	\$1,707
04	NAP	128			Near Saint Helena, at 1.2 miles east of Chiles Pope Valley Road. Construct retaining wall, rehabilitate drainage system, and install erosion control to stabilize slope.	2906G	4AA30	201.131	25/26	\$1,539	\$0	\$0	\$0	\$0	\$1,539	\$0	\$0	\$0	\$0	\$0	\$1,539
2020 SHOPP - Emergency Response TO											\$166,834	\$56,732	\$38,990	\$23,890	\$22,913	\$28,234	\$3,611	\$53,056	\$27,867	\$192,863	\$328,544
					SHOPP - Emergenc															\$194,865	•
								ROGRAMME												•	\$336,059
						SH	OPP - E	R DIFFERENC	E TOTAL	\$3,307	-\$6,982	\$0	\$1,010	\$8,899	\$3,307	\$3,693	\$244	\$896	\$0	-\$9,327	-\$1,187

April 27, 2022 5 of 5